

August 27, 2009 8:25:35 AM

Item ID:

D3161-7

A2

Revision ID:

Hinge 14.0" Item Name:

Required Date: 9/11/09

Start Date:

8/27/09

QC:

Start Qty: 10.00

Reg'd Qty: 10.00



Accept



Setup Start



Stop

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date: Tooling:

SPC (Y/N):

Date:

Date:

Run Start

Stop



Sequence ID/ **Work Center ID** Operation

Description

Set Up/ **Run Hours**

Draw Number **Draw** Rev.

Accept Plan Qty Code

Reject Qty

Reject Number Stamp

Insp.

Draw Nbr

Revision Nbr

D3161

Rev A2

Small Fab

Small Fab

Memo

Small Fab

(1) 72" Hinge makes (5) D3161-7 parts at 14" long Ocut to length as per Dwg

D3161

Memo

110

QC

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

0.00

120

Packaging

Identify as per dwg & Stock Location:



0.00

Memo

0.00

Packaging



Dart Aerospace Ltd

W/O:			WORK ORDER CHANGES							
DATE	STEP	PI	ROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
54.										
Part No	:	PAR #:	Fault Category:	NCR: Yes	s No DQ	A:	_ Date: _			
	Reso	lution:	Disposition:	QA: N/C	Closed:		Date: _			

NCR:	CR: WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC	Corrective Action Section B		Verification	action A		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
						;		
, 31776-								
			1					

						!		ļ

NOTE: Date & initial all entries

Work Order ID 51601

August 27, 2009 8:25:35 AM

Item ID:

D3161-7

Revision ID:

A2 Hinge 14.0"

Required Date: 9/11/09

Item Name: **Start Date:**

8/27/09

Start Qty: 10.00

Req'd Qty: 10.00

Reference:

Process Plan: Approvals:

QC:

Date:

Date:

Operation Description

QC21- Final Inspection - Work Order Release

Sequence ID/

130

Work Center ID

QC

Quality Control

Accept



Setup Start



Stop



Cust Item ID:

Customer:

Date:

Date:

Run Start

Stop



Draw Number Draw Rev.

Plan Code

Accept Qty

Reject Qty

Reject

Insp. Number Stamp

09/09/15 95/ M 09-9-15

Tooling:

SPC (Y/N):

Set Up/ Run Hours

0.00

0.00

Memo

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		

Part No:	[PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		NCR: WORK ORDER NON-CONFORMANCE (NCI						
		Description of NC	Description of NC Corrective Action Section B			Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto
							:	
						!	-	
						1		
							-	
						<u> </u>		

NOTE: Date & initial all entries

Picklist Print

August 27, 2009 8:25:34 AM

Work Order ID: 51601

Parent Item:

D3161-7RevA2

Parent Item Name: Hinge 14.0"

Comments:

Component Item ID/	Replacement	Mfg/
Item Name	Item ID	Purch

MS20257-3-7200

Purchased



Piano Hinge



Start Date: 8/27/09

Start Qty: 10.00

Required Date: 9/11/09

Required Qty: 10.00

Bin	Primar
Item	Locatio

No

Last Location

Route Seq ID

Unit of Measure Hand

Qty on

Remaining Qty Qty To Pick Issued

Date Issued

Status

100	Each	62.0000	10.0000

Warehouse	Loc Qty	Loc Code	
Location			,
Main Warehouse			
ST	62		
101334	4		
110267	19		
111072	39		
Mus			(10)

11/12611

Dart Aerospace Ltd

W/O:			WORK ORDER (CHANGES					
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Category:	NCR: Ye	s No DQ	A:	Date:		
	Resolu	tion:	Disposition:	QA: N/C	Closed:		Date:		

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)			
D.47-		Description of NC		Corrective Action Section B	3 .	Verification	Approval	A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto
,								<u> </u>
	ate & initial a							






DESIGN	DRAWN BY		OSPACE LTD ONTARIO, CANADA
CHECKED RF	APPROVED	DRAWING NO.	REV. A SHEET OF
DATE 02.0	4.24	TITLE HINGE	scale NTS

DART

1	0=.0=.54		111111111111111111111111111111111111111	1712
	Α	02.04.24	NEW ISUE	
	AI	+ 1 04.02.27	ADDED D3161-5	
	A 2	11-1-04.0630	800 03161-7 2 03161-9	~~~~~ ~~

<u> P/N</u>	LENGTH 'L'	DESCRIPTION
D3161-1	13.5"	HINGE (REPLACES MS 20257-3-13.5 ON D2183)
D3161-3	15.0"	HINGE (REPLACES MS 20257-3-150 ON D2950-041)
D3161-5	9,9"	HINGE
03161-7	14,0"	HINGE
03161-9	17.0"	HINGE.



NOTES:

(1) MAKE FROM MS20257-3-7200 HINGE

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.